## **NEW SITE IDENTIFICATION**

Pai	Part A – To Be Completed By Observer							
1.	Person Initiating Report: Jacob Harris	F	Phone: 526-1877					
	Contractor WAG Manager: Douglas Burns	F	Phone: 526-4324					
2.	Site Title: 009, Debris South of Highway 33 East of TAN	e Title: 009, Debris South of Highway 33 East of TAN						
3.	Describe the conditions that indicate a possible inactive or unreported waste site. Include location and description of suspicious condition, amount or extent of condition and date observed. A location map and/or diagram identifying the site against controlled survey points or global positioning system descriptors shall be included to help with the site visit. Include any known common names or location descriptors for the waste site.							
	There is a debris pile about 0.3 miles before mile marker 39 and 450 yards south of Highway 33. A dirt track that leads to t begins just west of the 600 East and Highway 33 intersection. During the July 1999 site visit, the observed surface debris i a 55 gallon drum (appears to be a burn barrel), rusted cans, glass, and some wood. The GPS coordinates of the site are E390133.426 by N791442.313. The reference number for this site is 009 and can be found on the summary map as provided.							
Pa	Part B – To Be Completed By Contractor WAG Manager							
4.	Recommendation:							
	This site meets the requirements for an inactive waste site, requires investigation, and should be included in the INEEL FFA/CO Action Plan. Proposed Operable Unit assignment is recommended to be included in the FFA/CO.  WAG: 10  Operable Unit: 10-08							
☐ This site DOES NOT meet the requirements for an inactive waste site, DOES NOT require investigation and SH6 included in the INEEL FFA/CO Action Plan.								
5. Basis for the recommendation:								
	The conditions that exist at this site indicate the potential for an inactive waste site according to Section 2 of MCP-3448 Reportin or Disturbance of Suspected Inactive Waste Sites.							
		¥						
	The basis for recommendation must include: (1) source description; (2) exposure pathways; (3) potential contaminants of concern; and (4) descriptions of interfaces with other programs, as applicable (e.g., D&D, Facility Operations, etc.)							
6.	Contractor WAG Manager Certification: I have examined the proposed site and the information submitted in this document and believe the information to be true, accurate, and complete. My recommendation is indicated in Section 4 above.							
Nai	me: Duglas E Burns Signature:	2	Date: 5/25/80					

## **NEW SITE IDENTIFICATION**

Part C – To Be Completed By INEEL FFACO/CO WAG Managers								
7. WAG Operable Unit:								
DOE WAG Manager Concurrence:	Concur with recomme	endation. 🔲 🛭	Do not concur wi	th the recommendation.				
Signature: Vatta Kroupa	_							
Date: 5/3/100 EAFWAG Managers Concurrence:	- ☑ Concur with recomme	andation $\square$ F	)a nat aanaur wii	th the recommendation				
Signature: Describer Signature:	A corredi with recomme	muzion. 🔲 L	o not concur wi	th the recommendation.				
Date: 6/5/00	_ _							
State of Idaho WAG Managers Concurrence:	,	endation. 🔲 🕻	o not concur wi	th the recommendation.				
Signature: Serve Mente:	<u>L</u>							
Date: 6-14-00 Explanation follows:	_							
Part D - To Be Completed By The INEEL FFA/CO Responsible Program Managers (RPM's)								
8. FFA/CO RPM's Concurrence:								
For DOE-ID Name: Kathleen Hain Signature: Zattlen	SHain Date: 7 11	2/00 1	Concur					
For EPA Region X			Do not concur.	Explanation follows:				
Name: Wayne Pierre Signature:	Cacoate: 1		- Concur Do not concur.	Explanation follows:				
For State of Idaho Name: Dean Nygard Signature:	lucad Date: 6/z	2/00 17	Concur					
Olyman Signatures	your Date. DIE		Do not concur.	Explanation follows:				



MISC-09, Debris South of Highway 33 East of TAN



MISC-09, Debris South of Highway 33 East of TAN



MISC-09, Debris South of Highway 33 East of TAN



MISC-09, Debris South of Highway 33 East of TAN



MISC-09, Debris South of Highway 33 East of TAN